

Work Order (Bid Form)

Knoxville/Knox County Community Action Committee



WORK ORDER INFORMATION

Work Order Name: WO/80008KN0618/1
Work Order Type: Weatherization
Audit Name: 80008KN0618-Audit

CLIENT INFORMATION

Client Name: Address:

Client ID: 80008KN0618

Alt. Client ID: Knox

AGENCY INFORMATION

Agency:Knoxville/Knox County CACAgency Phone:(865) 244-3080

Company Name & License Num	ber:	-	
Contractor's Signature:			

COMMENT

Single Family Dwelling

Contractor to follow 2006 International Residential Code as adopted by the City of Knoxville or Knox County as applicable.

City

House built in 1950

An EPA Certified Firm/Renovator is required.

Client Name:

Client ID: 80008KN0618

Alt. Client ID: Knox

Work Order (Bid Form)

Work Order Name: WO/80008KN0618/1

Report Run On: 5/6/2010

DOE Weatherization Assistant

Version 8.6.0 Page 1 of 10

Measures

,	Measure 1 Sla	b Door (D1, D2)			Componen	ts			Inspected
C	unit. A hinges,	re old door before installir door is inclusive of weath , threshold, facing, strike o be chos	erstripping	, door	lock, deadbo	olt, door	stop.		
					Estimated	·		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Unspecified	Slab Door (+)	Each	2			- Alexander and a second		
2	Labor	labor	Each	2		************			
	Other Detail								
				Measur	Sub Total:			Sub Total:	
	Field Notes:								-

Measure 2 DWH Pipe Insulati	,,,		Componen	Inspected				
Comment								
				Estimated			Actual	
# Material / Labor Description / C	omment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation DHW Pipe Insu	ulation	Each	1					
Includes labor corners must b properly. Refer Appendix A- St for Weatheriza Materials and S Field Guide.	e cut to tandards tion			<u> </u>			<u> </u>	
2 Labor DHW Pipe Insu	ulation	Each	1					
Other Detail								
]					
			easure	Sub Total:			Sub Total:	
Field Notes:								

1	Measure	3	Floo	r Ins. R-19			Componen	ts F1			Inspected
C		bet Sta sul (e. cor	fore in indare ofloor g. stat npres	s labor cost. Contractor estalling insulation. Cor ds. Insulation is installe above (paper side aga ves for blankets). Insu ssions. Refer to Appen theast Field Guide.	ntractor to in ed to mainta ainst subfloo llation to hav	stall u in per r) inclu /e NO	sing Resnet manent cont uding necess gaps, voids,	Resnet Grade 1 ent contact with the necessary supports s, voids, or			
							EstImated	'		Actual	
#	Material /	Lab	or	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	! Total
1	Insulation	ı		Floor Insulation - Fiberglass Batts - R-19	SqFt	264	To proper to a super				
2	Labor			Floor Insulation - Fiberglass Batts - R-19	SqFt	264					
C	Other Detail	<u> </u>									
					ı	Measur	e Sub Total:] 8	Sub Total:	
	Fleld Note	s:		**************************************							-

Comment extend pressure relief pipe as needed Estimated Actual # Material / Labor Description / Comment Units Qty Unit Cost Total Qty Unit Cost 1 Hot Water Equipm DHW Tank Insulation Each 1	
# Material / Labor Description / Comment Units Qty Unit Cost Total Qty Unit C	
	ost Total
1 Hot Water Equipm DHW Tank Insulation Each 1	
Includes labor cost. R-10 minimum. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.	
2 Labor DHW Tank Insulation Each 1	
Other Detail	
Measure Sub Total: Sub Total	al:
Fleid Notes:	

Report Run On: 5/6/2010

1	Measure	5	Floor	r Ins. R-19			Componen	ts F2			Inspected
C	comment	bef Sta sub (e.g	ore in indarc ifloor g. stav npres	stalling insulation. Con ls. Insulation is installe above (paper side agai res for blankets). Insul	s responsibility to seal penetration ractor to install using Resnet Grad d to maintain permanent contact which subfloor) including necessary sation to have NO gaps, voids, or lix A- Standards for Weatherization			Grade 1 act with t sary supp , or	the orts		
							Estimated	•		Actual	
#	Material /	Lab	or	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	1		Floor Insulation - Fiberglass Batts - R-19	SqFt	562		, , , , , , , , , , , , , , , , , , ,	Francisco		
2	Labor			Floor Insulation - Fiberglass Batts - R-19	SqFt	562					
C	Other Detai	,									

					i	Measur	e Sub Total: []	Sub Total:	TT 10 (10 (10 (10 (10 (10 (10 (10 (10 (10
	Field Note	s:									

Client ID: 80008KN0618
Alt. Client ID: Knox

DOE Weatherization Assistant Version 8.6.0

Report Run On: 5/6/2010

C	attic spa access. soffit and insulatin silicone access a Grade 1	s labor cost. Contractor to the ceshowing depth of insuface showing depth of insuface as needed dovering vent. Seal allow. Seal around chimney or fire resistant foam. In and weather strip with foar Standards. Refer to Apps and Southeast Field Gu	ulation. Buil to prever holes, gas with shees stall R-30 am tape. Opendix A-3	illd insi nt loose ps, an et meta fibergi Contrac	ulation dam a e fill insulation d penetration al and high te lass batt sec ctor to install	around a n from er ns in attic emperatu ured to a using Re	ttic ntering before re ttic esnet		
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Attic Insulation - Blown Fiberglass - R-19	SqFt	540				7,724	
2	Labor	Attic Insulation - Blown Fiberglass - R-19	SqFt	540	-				
C	Other Detail								
	.,,,,,								
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								

Components A1

Measure 6 Attic Ins. R-19

Inspected

,	weasure	/ CIX /	any Other Heating Sys	tem Probi	em	Compone	nts			mspecu
	omment	•Include Must pe Amana a approxir If size or install. Includes with involuted 6. This is Refer to Field Gu NOTE: Vone over pascals. allow. Install th	s labor cost. Must be instrorm an ACCA Manual or Goodman 13 Seer Spenately 1.5 ton. Final size of ACCA Manual J is different complete duct system. Sice. Must meet local coef boot to seal all seams. With appropriate caulk, as best performed with 2-Appendix A-Standards	stalled by a J and subrolit Heat Putor will be deserent from Must performed boots to boots all boots with a min I to Honey	i licens mit with imp, 10 termine this wi orm an I white ot where ie insul cell for erization oots of imum of well's I	red mechar invoice. Mo KW emer ed by the E rite up, con ACCA Mar Mastic to be re it meets lated on ou am. No cha on Material nust be belover 1 pasc of R6 insula	nical control flust be edigency he Director of tact CAC nual D and subfloor taide of banges allow and South 1 passes all but lessation. No Programme	qual to eat. Size for Housing before to entire to be count to Rowed. The east call with a than 3 changes	g. it e	
u	Adadatal /			** **		Estimate			Actual	
	Material / . Health ar		Description / Comment Replacement of Heating System	<i>Units</i> Each	Qty 1	Unit Cost	Total	Qty	Unit Cost	Total
2	Labor		Labor	Each	1					
o	ther Detail									
				ı	Measur	e Sub Total:]	Sub Total:	
	Field Note	s:								m, -r.

ctual nit Cost Total
nit Cost Total
V Adrian
Total:
ctual
it Cost Total
Total:
į

Client Name:

Client ID: 80008KN0618

Alt. Client ID: Knox

Work Order (Bid Form)

Work Order Name: WO/80008KN0618/1 Report Run On: 5/6/2010 DOE Weatherization Assistant

Version 8.6.0

Page 9 of 10